

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: June

Stock Number: 77921

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2019</u> Make: <u>Freightliner</u> Model: <u>Cascadia</u> Vin #: <u>2KK 4842</u>			
Engine: Make: <u>Detroit</u> Model: <u>DD15</u> HP: <u>505</u>			
Odometer Reading: <u>486,578</u> ECM Reading: <u>24,259</u>			
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>(NO)</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____
Brake Lining: Front R: <u>DISC</u> Tag Axle R: _____ L: _____ 1 st Axle R: <u>DISC</u> L: _____ 2 nd Axle R: <u>DISC</u> L: _____			
Tire Tread Percentage: Front: <u>50/50</u> Tag Axle: _____ 1 st Axle: <u>60/60</u> 2 nd Axle: <u>60/60</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 <u>8</u> 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: Steve Kinkade

Date: 5-30-24

Inspector Signature: Steve Kinkade

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***