

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: June

Stock Number: 78542

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Hockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2017 Make: Freightliner Model: Cascadia Vin #: 1H71415

Engine: Make: Detroit Model: DD13 HP: 435

Odometer Reading: 96,650

ECM Reading: 35,875

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): _____

Brake Lining: Front R: COVERS Tag Axle R: _____ L: _____ 1st Axle R: COVERS L: _____ 2nd Axle R: COVERS L: _____

Tire Tread Percentage: Front: 60/60 Tag Axle: _____ 1st Axle: 50/50 2nd Axle: 40/40

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: NO CEL

Other Comments: _____

Inspector Print: STEVE KINWAGE

Date: 6-6-24

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***