Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665 Auction Date: 6 **Stock Number: Lot Number:**

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS *** *** This is NOT A WARRANTY! ***

| Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: | | | | | |
|--|-----------|------------|--------------------|----------|----------------|
| Year: 2017 Make: <u>VOLVO</u> | | | | • | 979477 |
| Engine: Make: VOLVO Model: D13 HP: 428 | | | | | |
| Odometer Reading: 283, | 575 | EC | M Reading: 28 | 3,576 | |
| Task 1 | Yes | No | | Comments | |
| Does the Truck Start? | 2 | | Jump Start: YES or | NO. | |
| Does the motor idle and run normally? | X | | | | |
| Does the truck have the Emission Deleted? | | × | | | |
| Does the Transmission operate in all gears? | ~ | | | | |
| Does the Air load in normal time? | λ | | | | |
| Are there any fluid leaks? | · · | 1 | OIL OF COOLANT | | MAJOR or MINOR |
| Do you see coolant in the oil? | | | | | |
| Is the oil pressure at idle within OEM specs? | X | | | | |
| Is blow-by present? | 1 | | MAJOR OF MINOR |) | |
| Do you see oil in the coolant? | | | | | |
| Pressure check the cooling system | 12/4 | | PASS or FAIL | | |
| Is the clutch in good operating condition? | Au | 7) | Rate (1-10): | | |
| Brake Lining: Front R: CoverS Tag Axie R: L: 1st Axie R: 2nd Axie R: CoverS | | | | | |
| Tire Tread Percentage, Front: Tag Axle:1st Axle: 60602nd Axle: 60600 | | | | | |
| Comments: | | | | | |
| Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 | | | | | |
| Comments: NO | CE | <u></u> | | | |
| | | | | | |
| Other Comments: AIR LEAK TO REAR SUSP. PA65 | | | | | |

Inspector Print: STELL K

Date: 6-13-24

Inspector Signature:

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees lightle in any way ***