

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 8/9

Stock Number: 79363

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one) <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2017</u> Make: <u>INTERNATIONAL</u> Model: <u>PRO STAR</u> Vin #: <u>520766</u>			
Engine: Make: <u>CUMMINS</u> Model: <u>ISX</u> HP: <u>465</u>			
Odometer Reading: <u>595,213</u>		ECM Reading: <u>595,219</u>	
Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or <u>MINOR</u>
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____
Brake Lining: Front R: <u>Covers</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>Covers</u> L: _____ 2nd Axle R: <u>Covers</u> L: _____			
Tire Tread Percentage: Front: <u>60/60</u> Tag Axle: _____ 1st Axle: <u>40/40</u> 2nd Axle: <u>50/50</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: STEVE HUGHES

Date: 7-19-24

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***