## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 8/9
Stock Number: 79350
Lot Number:

WhITE

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): 8leeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:				
Year: <u>20/9</u> Make: <u>Vol Vo</u>	Model:	Vvi	860 Vin #:	211768
Engine: Make: Vocto Model: D3 HP:				
Odometer Reading: 669,053 ECM Reading: 669,054				
Task 7	Yes	No	Com	ments
Does the Truck Start?	7		Jump Start: YES or NO	
Does the motor idle and run normally?	×			<u> </u>
Does the truck have the Emission Deleted?		عر		
Does the Transmission operate in all gears?				
Does the Air load in normal time?	×			
Are there any fluid leaks?	<b>×</b>		Off or COOLANT	MAJOR or MUNOR
Do you see coolant in the oil?		X		
Is the oil pressure at idle within OEM specs?	<b>⅓</b>			
Is blow-by present?	4.	४	MAJOR or MINOR	
Do you see oil in the coolant?		χ		
Pressure check the cooling system	X		ASS or FAIL	
Is the clutch in good operating condition?	Au	40	Rate (1-10):	
Brake Lining: Front R:50 L:50 Tag Axle R: L: 1st Axle R:50 L:50 2nd Axle R:56 L:55				
Tire Tread Percentage: Front 50 85. Tag Axle: 1st Axle: 40 H D2nd Axle: _50 /5 O				
Comments:				
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10				
Comments:				
Other Comments: Broken Hoos Larg				
7.4.2				

Inspector Print: 5 Take X Marke

Date: 7-25-24

Inspector Signature: 5th Wh

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*