

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Oct

Stock Number: 81339

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2020 Make: Kenworth Model: 900 Vin #: 346839

Engine: Make: Cummins Model: 15X HP: 500

Odometer Reading: 604,639 ECM Reading: 604,679

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or <u>MINOR</u>
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>7</u>

Brake Lining: Front R: 80 L: 80 Tag Axle R: _____ L: _____ 1st Axle R: 50 L: 50 2nd Axle R: 50 L: 50

Tire Tread Percentage: Front: 50/60 Tag Axle: _____ 1st Axle: 60/60 2nd Axle: 40/40

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: _____

NO CHECK ENGINE LIGHTS

Other Comments: _____

Inspector Print: Steve Kivakos

Date: 9-11-24

Inspector Signature: SLK

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***