

Auction Date: 10/11  
Stock Number: ~~81657~~ 81661  
Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*  
\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2017 Make: VOLVO Model: VNL Vin #: 978225

Engine: Make: VOLVO Model: D13 HP: 425

Odometer Reading: 433,926 ECM Reading: 433,977

| Task  | Yes                                 | No                                  | Comments                      |
|---|-------------------------------------|-------------------------------------|-------------------------------|
| Does the Truck Start?                         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: Yes or <u>NO</u>  |
| Does the motor idle and run normally?         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Does the truck have the Emission Deleted?     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Does the Transmission operate in all gears?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Does the Air load in normal time?             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Are there any fluid leaks?                    | <input type="checkbox"/>            | <input type="checkbox"/>            | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Is blow-by present?                           | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | MAJOR or MINOR                |
| Do you see oil in the coolant?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Pressure check the cooling system             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>PASS</u> or FAIL           |
| Is the clutch in good operating condition?    | <u>Auto</u>                         | <input type="checkbox"/>            | Rate (1-10): _____            |

Brake Lining: Front R: 50/50 Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: 50 L: 50 2<sup>nd</sup> Axle R: 50 L: 50

Tire Tread Percentage: Front: 40/60 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 50/50 2<sup>nd</sup> Axle: 50/50

Comments: \_\_\_\_\_  
Cosmetic Condition: Rate 1 2 3 4 5 6 0 8 9 10

Comments: NO CHECK ENGINE LIGHTS

Other Comments: \_\_\_\_\_

Inspector Print: STEW KOVEAS

Date: 9-23-24

Inspector Signature: Stew Koveas

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

