## Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: \_\_ Stock Number: <u>825</u>32

**Lot Number:** 

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is **NOT A WARRANTY!** \*\*\*

Truck Type (Circle one): Sleeper Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:				
Year: 2020 Make: Mack		_		
Engine: Make: MACK Model: MB HP: 505  Odometer Reading: 355,435 ECM Reading: Churt Ken				
Odometer Reading: 355,435 ECM Reading: Churt Kew				
Task	Yes	No	Commen	ts
Does the Truck Start?	X		Jump Start: YES or NO	
Does the motor idle and run normally?	$\times$			**
Does the truck have the Emission Deleted?	7	$\searrow$		
Does the Transmission operate in all gears?	X	:		
Does the Air load in normal time?	<b>≫</b>			
Are there any fluid leaks?		$\lambda$	OIL or COOLANT	MAJOR or MINOR
Do you see coolant in the oil?		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Is the oil pressure at idle within OEM specs?	\ <u></u>			
Is blow-by present?		<b>*</b>	MAJOR or MINOR	
Do you see oil in the coolant?		X		
Pressure check the cooling system	4		PASS or FAIL	
Is the clutch in good operating condition?	Ay	*	Rate (1-10):	
Brake Lining: Front R: Tag Axle R: L: 1st Axle R: L: 2nd Axle R: L: 2nd Axle R: L:				
Tire Tread Percentage: Front: 60/60 Tag Axle:1st Axle: 30/30 2nd Axle: 40/40				
Comments:				
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10				
Comments: CHECK ENGINE LIGHT				
Other Comments:				
		<del></del>		

Inspector Print: 59% Kways

Date: 10-30-24

Inspector Signature: \_\_\_

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*