

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Dec. '24

Stock Number: 82087

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale **AS IS, WHERE IS** \*\*\*

\*\*\* This is **NOT A WARRANTY!** \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2017 Make: INTERNA Model: 4300 Vin #: 475020

Engine: Make: CUMMINS Model: B6.7L HP: 240

Odometer Reading: 449,641 ECM Reading: 449,643

Task	Yes	No	Comments
Does the Truck Start?	<u>2</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>2</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>1</u>		
Is blow-by present?	<u>1</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>1</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____

Brake Lining: Front R: COVERS L: \_\_\_\_\_ Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: COVERS L: \_\_\_\_\_ 2<sup>nd</sup> Axle R: \_\_\_\_\_ L: \_\_\_\_\_

Tire Tread Percentage: Front: 60/60 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 50/50 2<sup>nd</sup> Axle: \_\_\_\_\_

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NO CEL

Other Comments:

Serpentine belt is fraying

Inspector Print: STEVE KINAOE

Date: 11-20-24

Inspector Signature: Steve Kin

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*