

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Dec. '24

Stock Number: 81248

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>Freightliner</u> Model: <u>CASCADIA</u> Vin #: <u>HN5264</u>			
Engine: Make: <u>Detroit</u> Model: <u>DDC3</u> HP: <u>410</u>			
Odometer Reading: <u>319,228</u> ECM Reading: <u>53,237</u>			
Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or NO
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____
Brake Lining: Front R: <u>Disc</u> L: _____ Tag Axle R: _____ L: _____ 1 <sup>st</sup> Axle R: <u>Disc</u> L: _____ 2 <sup>nd</sup> Axle R: _____ L: _____			
Tire Tread Percentage: Front: <u>70/80</u> Tag Axle: _____ 1 <sup>st</sup> Axle: <u>60/50</u> 2 <sup>nd</sup> Axle: _____			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 7 8 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: SPRUE KIRKMAN

Date: 11-22-24

Inspector Signature: [Signature]

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

