

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blaga

Auction Date: Dec. 24  
Stock Number: 83190  
Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

| Truck Type (Circle one) <u>Sleeper</u> Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____                                         |                                     |                                     |                                             |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|---------------------------------------------|
| Year: <u>2019</u> Make: <u>Freightliner</u> Model: <u>CASCADIA</u> Vin #: <u>KD 8745</u>                                                                |                                     |                                     |                                             |
| Engine: Make: <u>DETROIT</u> Model: <u>DD15</u> HP: <u>505</u>                                                                                          |                                     |                                     |                                             |
| Odometer Reading: <u>698366</u> ECM Reading: <u>698,368</u>                                                                                             |                                     |                                     |                                             |
| Task                                                                                                                                                    | Yes                                 | No                                  | Comments                                    |
| Does the Truck Start?                                                                                                                                   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: YES or <u>NO</u>                |
| Does the motor idle and run normally?                                                                                                                   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Does the truck have the Emission Deleted?                                                                                                               | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                                             |
| Does the Transmission operate in all gears?                                                                                                             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Does the Air load in normal time?                                                                                                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Are there any fluid leaks?                                                                                                                              | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>OIL</u> or COOLANT MAJOR or <u>MINOR</u> |
| Do you see coolant in the oil?                                                                                                                          | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                                             |
| Is the oil pressure at idle within OEM specs?                                                                                                           | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                                             |
| Is blow-by present?                                                                                                                                     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | MAJOR or MINOR                              |
| Do you see oil in the coolant?                                                                                                                          | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                                             |
| Pressure check the cooling system                                                                                                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>PASS</u> or FAIL                         |
| Is the clutch in good operating condition?                                                                                                              | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Rate (1-10): _____                          |
| Brake Lining: Front R: <u>Disc</u> Tag Axle R: _____ L: _____ 1 <sup>st</sup> Axle R: <u>Disc</u> L: _____ 2 <sup>nd</sup> Axle R: <u>Disc</u> L: _____ |                                     |                                     |                                             |
| Tire Tread Percentage: Front: <u>70/70</u> Tag Axle: _____ 1 <sup>st</sup> Axle: <u>50/50</u> 2 <sup>nd</sup> Axle: <u>40/40</u>                        |                                     |                                     |                                             |
| Comments: _____                                                                                                                                         |                                     |                                     |                                             |
| Cosmetic Condition: Rate 1 2 3 4 5 6 7 <u>8</u> 9 10                                                                                                    |                                     |                                     |                                             |
| Comments: <u>NO CEL</u>                                                                                                                                 |                                     |                                     |                                             |
| Other Comments: <u>ABS Light</u>                                                                                                                        |                                     |                                     |                                             |

Inspector Print: Steve K... ..

Date: 11-22-24

Inspector Signature: Steve K...

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

