## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: APRIL 25
Stock Number: 84245

## HESS REPORT SHEET Lot Number:

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / paycab/ Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:				
Year: 2020 Make: Frughthen Model: CASCHOLA Vin#: 46889				
Engine: Make: DE Motel: DD 13 HP: 505				
Odometer Reading: 358, 723 ECM Reading: 358, 724				
Task	Yes	No	/ Comments	<b>&gt;</b>
Does the Truck Start?	$\rightarrow$		Jump Start: YES or (NO)	
Does the motor idle and run normally?	$\mathcal{X}$			
Does the truck have the Emission Deleted?		$\lambda$		
Does the Transmission operate in all gears?	ン			
Does the Air load in normal time?	×			
Are there any fluid leaks?		X	OIL or COOLANT	MAJOR or MINOR
Do you see coolant in the oil?	•	$\times$		
Is the oil pressure at idle within OEM specs?	<b>X</b>			
Is blow-by present?		$\lambda$	MAJOR or MINOR	
Do you see oil in the coolant?				
Pressure check the cooling system	4		PASS OF FAIL	
Is the clutch in good operating condition?	A	10	Rate (1-10):	
Brake Lining: Front R: Tag Axle R: L: 1st Axle R: L: 2nd Axle R: L: L: Tire Tread Percentage: Front: 50 50 Tag Axle: 1st Axle: 30 30 2nd Axle: 30 30				
Tire Tread Percentage: Front: 50/50 Tag Axle:1st Axle: 30/30 2nd Axle: 30/30				
Comments:				
Cosmetic Condition: Rate 1 2 3 4 5 6 (1) 8 9 10				
Comments: P/S GAK NO CEC				
Other Comments: Diffe Spot Peyfor Diturbly				
Inspector Print: SPGN HWAPA Date: Date: Date: 25-26-25				

Inspector Signature:

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*