

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: 4/13

Stock Number: 84330

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2021 Make: INTERNATIONAL Model: LT Vin #: 211384

Engine: Make: International Model: A26 HP: 475

Odometer Reading: 26423 P

ECM Reading: 261,230

Task	Yes	No	Comments
Does the Truck Start?	<u>2</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>2</u>		
Does the truck have the Emission Deleted?		<u>2</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____

Brake Lining: Front R: DISC L: _____ Tag Axle R: _____ L: _____ 1st Axle R: DISC L: _____ 2nd Axle R: DISC L: _____

Tire Tread Percentage: Front: 40/40 Tag Axle: _____ 1st Axle: 30/30 2nd Axle: 30/30

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

CZL ON

STOP ENGINE LIGHT ON

Other Comments:

DPF LIGHT ON / BROKEN PASS SIDE MIRROR

Inspector Print: Steve Knepper

Date: 3-7-28

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***