## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665

Blue

Auction Date:	4/11
Stock Number:	84354
Lot Number:	

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleepe (/ Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:					
Year: <u>2015</u> Make: <u>MCK</u> Model: <u>CX4613</u> Vin #: <u>047485</u>					
Engine: Make: WACK Model: MPS HP: 446					
Odometer Reading: 4376	46	EC	CM Reading: 967,64	8	
Task	Yes	No	Co	mments 💮	
Does the Truck Start?	7		Jump Start: YES or 📆		
Does the motor idle and run normally?	7				
Does the truck have the Emission Deleted?		7			
Does the Transmission operate in all gears?	<i>Y</i>				
Does the Air load in normal time?	×	490			
Are there any fluid leaks?	$\sim$		OID or COOLANT	MAJOR or MINOR	
Do you see coolant in the oil?	• •	~ <b>&gt;</b>			
Is the oil pressure at idle within OEM specs?	X				
Is blow-by present?		ン	MAJOR or MINOR		
Do you see oil in the coolant?		くく			
Pressure check the cooling system	4		PASS or FAIL		
Is the clutch in good operating condition?	-ـــــــــــــــــــــــــــــــــــــ	è	Rate (1-10):		
Brake Lining: Front R: Tag Axle R: L: 1 <sup>st</sup> Axle R: D <sup>15</sup> C L: 2 <sup>nd</sup> Axle R: L:					
Tire Tread Percentage Front: 50/50 Tag Axle: 1st Axle: 20/70 2nd Axle: 70/70					
Comments:					
Cosmetic Condition: Rate 1 2 3 4 5 5 7 8 9 10					
Comments: NO CEL					
Other Comments:					
Inspector Brint: SEA KANAN Date: 3-19-20					

Inspector Print: The Tyler

Inspector Signature

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*