

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: 4/11

Stock Number: 86004

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper/ Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: _____

Year: 2019 Make: Freightliner Model: CASCADIA Vin #: KC3889

Engine: Make: DEERE Model: DD13 HP: 505

Odometer Reading: 328,485 ECM Reading: 328,486

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	☒	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☒	MAJOR or MINOR
Do you see oil in the coolant?	☒	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Auto</u>

Brake Lining: Front R: DISC L: _____ Tag Axle R: _____ L: _____ 1st Axle R: DISC L: _____ 2nd Axle R: _____ L: _____

Tire Tread Percentage: Front 60/60 Tag Axle: _____ 1st Axle: 30/30 2nd Axle: 30/30

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: NO CEL

Other Comments: _____

Inspector Print: Steve Koutz

Date: 3-18-25

Inspector Signature: Steve Koutz

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***