## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: _	4/11
Stock Number:	84497

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:					
Year: 2016 Make: Reightlinen	Model	CAS CA	cha 113 Vin#:	GT8504	
Engine: Make: DETROIT Model: DD 13 HP: 410					
Odometer Reading: 960,2	66	EC	CM Reading: 960, 269		
Task	Yes	No	Comments		
Does the Truck Start?	7		Jump Start: YES or No.		
Does the motor idle and run normally?	7			1	
Does the truck have the Emission Deleted?		X			
Does the Transmission operate in all gears?	X	-	A CONTRACT OF THE CONTRACT OF	**************************************	
Does the Air load in normal time?	\forall \forall \cdot \c			<del></del>	
Are there any fluid leaks?		V	OIL or COOLANT	MAJOR or MINOR	
Do you see coolant in the oil?		\\ <b>\</b>			
Is the oil pressure at idle within OEM specs?	1				
Is blow-by present?			MAJOR or MINOR		
Do you see oil in the coolant?		$\langle \langle \boldsymbol{\chi} \rangle \rangle$	<i>y</i>		
Pressure check the cooling system	16		PASS or FAIL		
Is the clutch in good operating condition?	AU	uto)	Rate (1-10):		
Brake Lining: Front R: DISC Tag Axle R: L: 1st Axle R: L: 2nd Axle R: L:					
Tire Tread Percentage; Front: 40/40_ Tag Axle: 1st Axle 20/30 2nd Axle: 20/70					
Comments:					
Cosmetic Condition: Rate 1 2 3 4 5 7 8 9 10  Comments:  Output  Description: Rate 1 2 3 4 5 7 8 9 10					
Other Comments:					
		ŧ			

Inspector Print: 51814 Killians

Date: 3-25-25

Inspector Signature: She last

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*