## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665

| Auction Date: | APRIL | 25 |
|---------------|-------|----|
| Stock Number  | 86160 |    |
| Lot Number:   |       |    |

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is **NOT A WARRANTY!** \*\*\*

| Truck Type (Circle one): Sleeper / Daycab  | / Jockey / | Dump / E   | Box / Flatbed / Reefer/ Chassis / Othe | er:            |  |
|--|------------|------------|--|----------------|--|
| Year: 2017 Make: <b>INT'</b> L   | Model      | PRO        | SPAR Vin #: 428997                     |                |  |
| Engine: Make: Model: N/3 HP: 390   |            |            |  |                |  |
| Odometer Reading: 254, 274 ECM Reading: 254, 271                                   |            |            |  |                |  |
| Task   | Yes        | No         | Comments                               |                |  |
| Does the Truck Start?  | X          |            | Jump Start: YES-or NO                  | ***            |  |
| Does the motor idle and run normally?  | 7          |            |  |                |  |
| Does the truck have the Emission Deleted?  |            | يلم        |  |                |  |
| Does the Transmission operate in all gears?  | $\lambda$  |            |  |                |  |
| Does the Air load in normal time?  | $\searrow$ |            |  |                |  |
| Are there any fluid leaks?   |            | $\lambda$  | OIL or COOLANT                         | MAJOR or MINOR |  |
| Do you see coolant in the oil?   | 1          | X          |  |                |  |
| Is the oil pressure at idle within OEM specs?                                      | X          | 1          |  |                |  |
| Is blow-by present?  |            | \ <b>\</b> | MAJOR or MINOR                         |                |  |
| Do you see oil in the coolant?   |            | X          |  |                |  |
| Pressure check the cooling system  |            | <b>?</b> \ | PASS OF FAIL                           |                |  |
| Is the clutch in good operating condition?   | Au         | 0          | Rate (1-10):                           |                |  |
| Brake Lining: Front R: 60 L: 60 Tag Axie R: L: 1st Axie R: 30 L: 36 2nd Axie R: L: |            |            |  |                |  |
| Tire Tread Percentage: Front Holy Tag Axle:1st Axle:1st Axle:                      |            |            |  |                |  |
| Comments:  |            |            |  |                |  |
| Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10  Comments:                           |            |            |  |                |  |
| Other Comments: Low Cooket   |            |            |  |                |  |
| Inspector Print: The Harden Date: 3-76-75  |            |            |  |                |  |

Inspector Signature:

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*