## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665 Auction Date: APRA &
Stock Number: 86517

**Lot Number:** 

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is **NOT A WARRANTY!** \*\*\*

| Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: |          |                                     |                        |   |
|--|----------|-------------------------------------|------------------------|---|
| Year: <b>2016</b> Make: <b>VOLVO</b>   | Model    | · VN                                | L Vin#: 93387          | 6   |
| Engine: Make: Volvo Model: DB HP: 425  |          |                                     |                        |   |
| Odometer Reading: 64,775 ECM Reading: 614,777  |          |                                     |                        |   |
| Task ,   | Yes      | No                                  | Comments               | <u>. }                                   </u> |
| Does the Truck Start?  | <u> </u> |                                     | Jump Start: YES or No. |   |
| Does the motor idle and run normally?  | <i>≥</i> |                                     |                        |   |
| Does the truck have the Emission Deleted?  |          | <u>ح</u>                            |                        |   |
| Does the Transmission operate in all gears?  | ×        |                                     |                        |   |
| Does the Air load in normal time?  |          |                                     |                        |   |
| Are there any fluid leaks?   |          | ×                                   | OIL or COOLANT         | MAJOR or MINOR                                |
| Do you see coolant in the oil?   |          | $\times$                            |                        |   |
| Is the oil pressure at idle within OEM specs?  | 7        |                                     |                        |   |
| Is blow-by present?  |          | $\rightarrow$                       | MAJOR or MINOR         |   |
| Do you see oil in the coolant?   |          | ×                                   |                        |   |
| Pressure check the cooling system  | $\chi$   | $\mathcal{L} \setminus \mathcal{L}$ | PASS of FAIL           |   |
| Is the clutch in good operating condition?   | Dy       | to                                  | Rate (1-10):           |   |
| Brake Lining: Front R: 60 L: 60 Tag Axle R: 1st Axle R: 50 L: 56 2nd Axle R: 50 L: 56                |          |                                     |                        |   |
| Tire Tread Percentage: Front: 50 5 6 Tag Axle:1st Axle: 40/40  |          |                                     |                        |   |
| Comments:  |          |                                     |                        |   |
| Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10  |          |                                     |                        |   |
| Comments: NO CEL   |          |                                     |                        |   |
| Other Comments:  |          |                                     |                        |   |
| Inspector Print: State: 4Man Date: 3-31-26   |          |                                     |                        |   |

Inspector Signature: \*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*