

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: APRIL '25
Stock Number: 86546
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2018</u> Make: <u>Kenworth</u> Model: <u>T680</u> Vin #: <u>192956</u>			
Engine: Make: <u>Isuzu</u> Model: <u>MX13</u> HP: <u>455</u>			
Odometer Reading: <u>870,767</u> ECM Reading: <u>541,059</u>			
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start <u>YES</u> or NO
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	OIL or <u>COOLANT</u> MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or <u>FAIL</u>
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>5</u>
Brake Lining: Front R: <u>DISC</u> L: _____ Tag Axle R: _____ L: _____ 1 st Axle R: <u>50</u> L: <u>50</u> 2 nd Axle R: <u>50</u> L: <u>50</u>			
Tire Tread Percentage: Front: _____ Tag Axle: _____ 1 st Axle: <u>40/40</u> 2 nd Axle: <u>40/40</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 <u>6</u> 8 9 10			
Comments: <u>CEL ON / ABS</u>			
Other Comments: <u>COOLANT LEAK</u>			

Inspector Print: Steve W. K...

Date: 4-2-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***