

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 4/11
Stock Number: 84385
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: OTTAWA Model: 4x2 Vin #: 001258

HR3-13,013 Engine: Make: Cummins Model: B6.7L HP: 200

Odometer Reading: 5533 ECM Reading: 17,479 HRS 13,014

Task	Yes	No	Comments
Does the Truck Start?	<u>2</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>2</u>		
Does the truck have the Emission Deleted?		<u>2</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<u>X</u>	<u>X</u>	
Is the oil pressure at idle within OEM specs?			
Is blow-by present?	<u>X</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?		<u>Auto</u>	Rate (1-10): _____

Brake Lining: Front R: 60 L: 60 Tag Axle R: _____ L: _____ 1st Axle R: 60 L: 60 2nd Axle R: _____ L: _____

Tire Tread Percentage: Front: 60/60 Tag Axle: _____ 1st Axle: 70/70 2nd Axle: _____

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: DPF LIGHT ON / CEL ON

Other Comments: _____

Inspector Print: Steve Hanks

Date: 3-20-25

Inspector Signature: Steve Hanks

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***