

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: APRIL 25
Stock Number: 84448
Lot Number: _____

MAKROON HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2020</u> Make: <u>Kenworth</u> Model: <u>T680</u> Vin #: <u>357505</u>			
Engine: Make: <u>Cummins</u> Model: <u>X15</u> HP: <u>450</u>			
Odometer Reading: <u>591,430</u>		ECM Reading: <u>591,431</u>	
Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____
Brake Lining: Front R: <u>Disc</u> Tag Axle R: _____ L: _____ 1 st Axle R: <u>60</u> L: <u>60</u> 2 nd Axle R: <u>60</u> L: <u>60</u>			
Tire Tread Percentage: Front: <u>50/50</u> Tag Axle: _____ 1 st Axle: <u>50/50</u> 2 nd Axle: <u>50/50</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 <u>8</u> 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: STEVE KUKAPO

Date: 3-21-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***