

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: APRIL '25

Stock Number: 86140

Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2021 Make: AUTOLAR Model: ACX SP1000 Vin #: 233554

Engine: Make: Commin Model: B67L HP: 200

Odometer Reading: 48,921 ECM Reading: 47,51 HRS 15,142

| Task  | Yes                                 | No                                  | Comments                      |
|---|-------------------------------------|-------------------------------------|-------------------------------|
| Does the Truck Start?                         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Jump Start: YES or <u>NO</u>  |
| Does the motor idle and run normally?         | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Does the truck have the Emission Deleted?     | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Does the Transmission operate in all gears?   | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Does the Air load in normal time?             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Are there any fluid leaks?                    | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |                               |
| Is blow-by present?                           | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | MAJOR or MINOR                |
| Do you see oil in the coolant?                | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |                               |
| Pressure check the cooling system             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <u>PASS</u> or FAIL           |
| Is the clutch in good operating condition?    | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | Rate (1-10): _____            |

Brake Lining: Front R: COS L: COS Tag Axle R: COS L: COS 1<sup>st</sup> Axle R: COS L: COS 2<sup>nd</sup> Axle R: COS L: COS

Tire Tread Percentage: Front: 70/20 Tag Axle: 70/20 1<sup>st</sup> Axle: 70/20 2<sup>nd</sup> Axle: 70/20

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

CEL ON

Other Comments:

Inspector Print: STEVE KOMPAS

Date: 3-25-25

Inspector Signature: Steve Kompas

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*