## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665

Auction Date: \_\_\_\_\_\_ Stock Number:

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

| *** This is <b>NOT A WARRANTY!</b> ***   |           |      |                       |                |
|--|-----------|------|-----------------------|----------------|
| Truck Type (Circle one): Sleeper Daycab Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: |           |      |                       |                |
| Year: 2017 Make: VOVO Model: VNL Vin#: 988842  |           |      |                       |                |
| Engine: Make: WWD Model: D13 HP: 435  Odometer Reading: 606,635  ECM Reading: 606,635            |           |      |                       |                |
| Odometer Reading: 606,625 ECM Reading: 606,625   |           |      |                       |                |
| Task   | Yes       | No   | Comm                  | ents           |
| Does the Truck Start?  | 1         |      | Jump Start: YES or NO |                |
| Does the motor idle and run normally?  | 1         | -    |                       |                |
| Does the truck have the Emission Deleted?  |           | X    |                       |                |
| Does the Transmission operate in all gears?  | $\lambda$ | :    |                       |                |
| Does the Air load in normal time?  | ×         |      |                       |                |
| Are there any fluid leaks?   |           | ×    | OIL or COOLANT        | MAJOR or MINOR |
| Do you see coolant in the oil?   |           | ×    |                       |                |
| Is the oil pressure at idle within OEM specs?  | $\lambda$ |      |                       |                |
| Is blow-by present?  |           | X    | MAJOR or MINOR        |                |
| Do you see oil in the coolant?   |           | K    |                       |                |
| Pressure check the cooling system  | $\lambda$ | . (  | PASS Or FAIL          |                |
| Is the clutch in good operating condition?   | Au        | to ) | Rate (1-10):          |                |
| Brake Lining: Front R: 50 L36 Tag Axle R: L: 1st Axle R: 20 L: 2nd Axle R: 40 L: 40              |           |      |                       |                |
| Tire Tread Percentage: Front: 10/50 Tag Axle: 1st Axle: 40/40 2nd Axle: 60/60                    |           |      |                       |                |
| Comments:  |           |      |                       |                |
| Cosmetic Condition: Rate 1 2 3 4 5 6 8 9 10  |           |      |                       |                |
| Comments: NO GL  |           |      |                       |                |
|  |           |      |                       |                |
| Other Comments:  |           |      |                       |                |
| Inspector Print: Kinkapi, Date: 5-7-35   |           |      |                       |                |

Inspector Signature:

\*\*\* This report is performed a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*