

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: 6/13

Stock Number: 86864

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: VOLVO Model: VNL Vin #: 951591

Engine: Make: VOLVO Model: D13 HP: 500

Odometer Reading: 761,632 ECM Reading: 761,634

| Task | Yes | No | Comments |
|---|-------------------------------------|-------------------------------------|---|
| Does the Truck Start? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Jump Start: YES or <u>NO</u> |
| Does the motor idle and run normally? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the truck have the Emission Deleted? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Does the Transmission operate in all gears? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the Air load in normal time? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Are there any fluid leaks? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <u>OIL</u> or COOLANT MAJOR or <u>MINOR</u> |
| Do you see coolant in the oil? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Is blow-by present? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <u>MAJOR</u> or MINOR |
| Do you see oil in the coolant? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Pressure check the cooling system | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <u>PASS</u> or FAIL |
| Is the clutch in good operating condition? | <u>Auto</u> | <input type="checkbox"/> | Rate (1-10): _____ |

Brake Lining: Front R: DISC L: _____ Tag Axle R: _____ L: _____ 1st Axle R: DISC L: _____ 2nd Axle R: DISC L: _____

Tire Tread Percentage: Front: 30/30 Tag Axle: _____ 1st Axle: 40/40 2nd Axle: 30/30

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

CEL ON

Other Comments: _____

Inspector Print: Steve Kivimäki

Date: 5-7-25

Inspector Signature: Steve Kivimäki

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***