## **Hess Auctioneers, LLC.**

Bluc.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665

Auction Date: <u>0-13-25</u>

Stock Number: 87041

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other:				
Year: 2023 Make: Kenworth	<u>)</u> Model	T88	O Vin #:	236969
Engine: Make: Model: Model: HP: HP:				
Odometer Reading: 50, 44 ECM Reading: 51, 133				
Task	Yes	No	Comment	ts
Does the Truck Start?	$\sim$		Jump Start: YES or NO	
Does the motor idle and run normally?	7			
Does the truck have the Emission Deleted?		人		
Does the Transmission operate in all gears?	1			
Does the Air load in normal time?	~	/		
Are there any fluid leaks?		V	OIL or COOLANT	MAJOR or MINOR
Do you see coolant in the oil?	. 1	X		
Is the oil pressure at idle within OEM specs?	Y			
Is blow-by present?		X	MAJOR or MINOR	E
Do you see oil in the coolant?		X		
Pressure check the cooling system	X	F	PASS or AIL	
Is the clutch in good operating condition?			Rate (1-10):	
Brake Lining: Front R: Tag Axle R: L: 1st Axle R: L: 2nd Axle R: L:				
Tire Tread Percentage: Front: DO Tag Axle: 1st Axle: 2nd Axle: 2nd Axle: 40 60				
Comments:				
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10				
Comments: PO	Cal			
Other Comments:				

Inspector Print: SPUR KIWARA

Inspector Signature:

Inspector Signature:

\*\*\* This report is performed as a guide for your buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*