

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665

Silver

Auction Date: JUNE '25 ~~8/15~~

Stock Number: 87145

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2023 Make: VOLVO Model: VNL860 Vin #: 625305

Engine: Make: VOLVO Model: D13 HP: 500

Odometer Reading: 248,474 ECM Reading: 248,474

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: Yes or <u>No</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☐	☒	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	<u>Auto</u>	☐	Rate (1-10): _____

Brake Lining: Front R: Disc L: _____ Tag Axle R: _____ L: _____ 1st Axle R: Disc L: _____ 2nd Axle R: Disc L: _____

Tire Tread Percentage: Front: 50/50 Tag Axle: _____ 1st Axle: 70/70 2nd Axle: 60/50

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 9

Comments:

No CEL

Other Comments: _____

Inspector Print: Steve Kinnick

Date: 5-12-25

Inspector Signature: Steve Kinnick

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***