

Hess Auctioneers, LLC.

White

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 6/13/25Stock Number: 87214

Lot Number: _____

HESS REPORT SHEET*** ALL Trucks are For Sale **AS IS, WHERE IS** ****** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2017</u> Make: <u>Kenworth</u> Model: <u>T680</u> Vin #: <u>162283</u>			
Engine: Make: <u>Cummins</u> Model: <u>15X15</u> HP: <u>500</u>			
Odometer Reading: <u>714,545</u>		ECM Reading: <u>CAN'T READ</u>	
Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start <u>YES</u> or NO
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☒	☐	<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?	☒	☐	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	<u>MAJOR</u> or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>5</u>
Brake Lining: Front R: <u>DWC</u> L: _____ Tag Axle R: _____ L: _____ 1 st Axle R: <u>Disc</u> L: _____ 2 nd Axle R: <u>Disc</u> L: _____			
Tire Tread Percentage: Front: <u>30/36</u> Tag Axle: _____ 1 st Axle: <u>40/40</u> 2 nd Axle: <u>40/40</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10			
Comments: <u>CEL ON</u>			
Other Comments: _____			

Inspector Print: Steve KinsaleDate: 5-16-25Inspector Signature: [Signature]*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***