

Hess Auctioneers, LLC.

white

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 6-13-25

Stock Number: 87294

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2016</u> Make: <u>VOLVO</u> Model: <u>VNL</u> Vin #: <u>933818</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D13</u> HP: <u>425</u>			
Odometer Reading: <u>535,264</u> ECM Reading: <u>535,216</u>			
Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or NO
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☐	☒	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____
Brake Lining: Front R: <u>60</u> L: <u>60</u> Tag Axle R: _____ L: _____ 1 st Axle R: <u>50</u> L: <u>50</u> 2 nd Axle R: <u>50</u> L: <u>50</u>			
Tire Tread Percentage: Front: <u>50/50</u> Tag Axle: _____ 1 st Axle: <u>50/50</u> 2 nd Axle: <u>50/50</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: SPENCER HUNTER

Date: 5-21-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***