

Hess Auctioneers, LLC.

white

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 6-13-25

Stock Number: 87382

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2017 Make: VOLVO Model: VNL Vin #: 978241

Engine: Make: VOLVO Model: D13 HP: 425

Odometer Reading: 550,337 ECM Reading: 550,339

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>Auto</u>
Brake Lining: Front R: <u>70</u> L: <u>70</u> Tag Axle R: _____ L: _____ 1 st Axle R: <u>50</u> L: <u>50</u> 2 nd Axle R: <u>50</u> L: <u>50</u>			
Tire Tread Percentage: Front: <u>60/60</u> Tag Axle: _____ 1 st Axle: <u>40/40</u> 2 nd Axle: <u>50/50</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: JEFF KIRK

Date: 5-27-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***