## **Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665 Auction Date: 613.25

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\* \*\*\* This is NOT A WARRANTY! \*\*\*

| Truck Type (Circle one): Sleeper (Daycab) Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: |       |              |                 |          |   |
|--|-------|--------------|-----------------|----------|---|
| Year: 2019 Make: Mack  | Model | ı: <u>Ar</u> | them Vin#:      | 0079     | 59                                      |
| Engine: Make: MAC  | κ     | _ Model:     | MP8             | HP:      | _                                       |
| Odometer Reading: 434,383 ECM Reading: 434,354   |       |              |                 |          |   |
| Task   | Aes   | No           |                 | Comments |   |
| Does the Truck Start?  | X     |              | Jump Start: VES | or NO    |   |
| Does the motor idle and run normally?  | 1     |              |                 |          |   |
| Does the truck have the Emission Deleted?  |       | $\lambda$    |                 |          |   |
| Does the Transmission operate in all gears?  | \ \   |              |                 |          | *************************************** |
| Does the Air load in normal time?  | V     |              |                 |          | · · · · · · · · · · · · · · · · · · ·   |
| Are there any fluid leaks?   | 人     |              | OD COOLANT      |          | MAJOR OF MINOR                          |
| Do you see coolant in the oil?   | 1     | 1            |                 |          |   |
| Is the oil pressure at idle within OEM specs?  | 1     |              |                 |          |   |
| Is blow-by present?  |       |              | MAJOR or MINO   | R        |   |
| Do you see oil in the coolant?   | 18/10 | X            |                 |          |   |
| Pressure check the cooling system  | 44    |              | PASS or FAIL    |          | *************************************** |
| Is the clutch in good operating condition?   | Au.   | +2           | Rate (1-10):    | _        |   |
| Brake Lining: Front R: DIE Tag Axle R: L: 1st Axle R: 2nd Axle R: L: L: L:                         |       |              |                 |          |   |
| Tire Tread Percentage Front: Tag Axle: 1st Axle: 20/30 2nd Axle: 30/20                             |       |              |                 |          |   |
| Comments:  |       |              |                 |          |   |
| Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10  |       |              |                 |          |   |
| CEL Comments:  | 8N    | )            |                 |          |   |
| Other Comments: Low Coolant Level / NO PASS SIDE MITTOR  |       |              |                 |          |   |
| Inspector Print: State Livere Date: 5-27-25  |       |              |                 |          |   |
| # 1/   |       |              |                 |          |   |

Inspector Signature:

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*