

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

white

Auction Date: 6/13
Stock Number: 87541
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2019 Make: Freightliner Model: CASCADIA Vin #: KW0716

Engine: Make: CUMMINS Model: X15 HP: 560

Odometer Reading: 567,085 ECM Reading: 567,086

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>7</u>

Brake Lining: Front R: DISC Tag Axle R: DISC L: DISC 1st Axle R: DISC L: DISC 2nd Axle R: DISC L: DISC

Tire Tread Percentage: Front: 50/50 Tag Axle: 40/40 1st Axle: 40/40 2nd Axle: 40/40

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NO CEL

Other Comments:

Inspector Print: Steve Krupke

Date: 5-30-25

Inspector Signature: Steve Krupke

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***