

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Blue

Auction Date: 6/13
Stock Number: 87537
Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2019 Make: Freightliner Model: Cascadia Vin #: KF4716

Engine: Make: Deere Model: DD15 HP: 400

Odometer Reading: 678,569 ECM Reading: 570,079

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>Yes</u> or <u>No</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☐	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☐	☒	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): <u>Auto</u>

Brake Lining: Front R: 60 60 Tag Axle R: _____ L: _____ 1st Axle R: 50 L: 50 2nd Axle R: 30 L: 30

Tire Tread Percentage: Front: 60/60 Tag Axle: _____ 1st Axle: 60/60 2nd Axle: 50/50

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 9

Comments:

Other Comments: DEF GAGE not working

Inspector Print: RAE Kuehl

Date: 6/2/25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***