## Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date:	6/13/25
Stock Number:	876a1

Lot Number:

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Total Total Colonia	- P A n 8			2 / 2-1
Truck Type (Circle one) (Sleeper) Dayo				
Year: <u>202</u> Make: <u>VOVC</u>	Mode	1: <u>V</u>	<u> VL760</u> vin#: <u> </u>	62889
Engine: Make: <u>Vo</u>	WO	_ Model:	D13 HP: Y	53_
Odometer Reading: <u>434</u>			CM Reading: 436,56	4
Task	1 Yes	No	1000	ments 💙
Does the Truck Start?	1		Jump Start: Singrate	
Does the motor idle and run normally?	1 2	·		
Does the truck have the Emission Deleted?		7		
Does the Transmission operate in all gears?	1			
Does the Air load in normal time?	12			
Are there any fluid leaks?			DIL of COOLANT	MAJOR or MINOR
Do you see coolant in the oil?				
Is the oil pressure at idle within OEM specs?	X			
Is blow-by present?		V	MAJOR or MINOR	
Do you see oil in the coolant?		X		
Pressure check the cooling system		<b>\</b>	PASS or FAIL	
Is the clutch in good operating condition	Att	0	Rate (1-10):	
Brake Lining: Front R: 50 50 Tag Ave R: L: 1st Axle R: 60 L: 60 2nd Axle R: 50 L: 50				
Tire Tread Percentage Front: 10 St Tag Axie:1st Axie: 40/40 2nd Axie: 40/40				
Comments:		•		
Cosmetic Co			3 4 5 6 7 (3) 9 10	
Comments:	NO		il.	•
Other Comments:				
· · · · · · · · · · · · · · · · · · ·				

Inspector Print: STEBE KM/

Date: 5-3-25

Inspector Signature:

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*