

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Red

Auction Date: 6/13

Stock Number: 87603

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2017 Make: International Model: Prostar Vin #: 520758

Engine: Make: Cummins Model: LSX HP: 475

Odometer Reading: 617,856 ECM Reading: 617,858

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>YES</u> or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☒	☐	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	PASS or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____
Brake Lining: Front R: <u>Covers</u> Tag Axle R: _____ L: _____ 1st Axle R: <u>Covers</u> L: _____ 2nd Axle R: <u>Covers</u> L: _____			
Tire Tread Percentage: Front: <u>50/60</u> Tag Axle: _____ 1st Axle: <u>60/60</u> 2nd Axle: <u>60/60</u>			
Comments:			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments:			<u>See on</u>
Other Comments:			

Inspector Print: Steve K...

Date: 6-4-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***