

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 8-8-25

Stock Number: 87833

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2018 Make: Freightliner Model: Cascadia Vin #: JN4891

Engine: Make: Isuzu Model: DD15 HP: 455

Odometer Reading: 825,599 ECM Reading: CAN'T READ

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: <u>Yes</u> or <u>No</u>
Does the motor idle and run normally?	☐	☒	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☒	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☐	☒	
Is blow-by present?	☐	☒	MAJOR or MINOR
Do you see oil in the coolant?	☐	☒	
Pressure check the cooling system	☒	☐	PASS or <u>FAIL</u>
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____

Brake Lining: Front R: 30 30 Tag Axle R: _____ L: _____ 1st Axle R: 60 L: 60 2nd Axle R: 40 L: 40

Tire Tread Percentage: Front: 30/80 Tag Axle: _____ 1st Axle: 30/30 2nd Axle: 30/30

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: CEL ON

Other Comments: _____

Inspector Print: Steve K...

Date: 8-30-25

Inspector Signature: Steve K...

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***