

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: AUG '25

Stock Number: 07934

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: SERVICE TRUCK

Year: 2016 Make: PETERBILT Model: 337 Vin #: 345975

Engine: Make: PACCAR Model: PX7 HP: 325

Odometer Reading: 282,358 ECM Reading: 279,027

| Task | Yes | No | Comments |
|---|-------------------------------------|-------------------------------------|-------------------------------------|
| Does the Truck Start? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Jump Start: <u>YES</u> or <u>NO</u> |
| Does the motor idle and run normally? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the truck have the Emission Deleted? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Does the Transmission operate in all gears? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Does the Air load in normal time? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Are there any fluid leaks? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Is the oil pressure at idle within OEM specs? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| Is blow-by present? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | MAJOR or MINOR |
| Do you see oil in the coolant? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Pressure check the cooling system | <input checked="" type="checkbox"/> | <input type="checkbox"/> | PASS or FAIL |
| Is the clutch in good operating condition? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Rate (1-10): <u>5</u> |

Brake Lining: Front R: 80 80 Tag Axle R: _____ L: _____ 1st Axle R: 80 L: 80 2nd Axle R: _____ L: _____

Tire Tread Percentage: Front 80/80 Tag Axle: _____ 1st Axle: 60/60 2nd Axle: _____

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NO CEL

Other Comments: _____

Inspector Print: SPUR KINZADE

Date: 7-3-25

Inspector Signature: Steve Kail

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***