

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Yellow

Auction Date: 10/10/17

Stock Number: 89628

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2020 Make: International Model: RH613 Vin #: 845187

Engine: Make: Int'l Model: A26 HP: _____

Odometer Reading: 508,004 ECM Reading: 265,128

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or NO
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?	<u>X</u>	<u>X</u>	
Pressure check the cooling system	<u>X</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____

Brake Lining: Front R: Disco L: _____ Tag Axle R: _____ L: _____ 1st Axle R: Disco L: _____ 2nd Axle R: Disco L: _____

Tire Tread Percentage: Front 50/80 Tag Axle: _____ 1st Axle: 60/60 2nd Axle: 70/70

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: NO CEL

Other Comments: _____

Inspector Print: Steve Kmetz

Date: 8-27-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***