

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Yellow

Auction Date: 10/10

Stock Number: 89630

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / <u>Daycab</u> / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2020</u> Make: <u>International</u> Model: <u>RH613</u> Vin #: <u>089746</u>			
Engine: Make: <u>ISUZU</u> Model: <u>A26</u> HP: _____			
Odometer Reading: <u>539,081</u> ECM Reading: <u>539,028</u>			
Task	Yes	No	Comments
Does the Truck Start?	<u>✓</u>		Jump Start: YES or NO
Does the motor idle and run normally?	<u>✓</u>		
Does the truck have the Emission Deleted?		<u>✓</u>	
Does the Transmission operate in all gears?	<u>✓</u>		
Does the Air load in normal time?	<u>✓</u>		
Are there any fluid leaks?		<u>✓</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>✓</u>	
Is the oil pressure at idle within OEM specs?	<u>✓</u>		
Is blow-by present?		<u>✓</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>✓</u>	
Pressure check the cooling system	<u>✓</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____
Brake Lining: Front R: <u>DISC</u> L: _____ Tag Axle R: _____ L: _____ 1 st Axle R: <u>DISC</u> L: _____ 2 nd Axle R: <u>DISC</u> L: _____			
Tire Tread Percentage: Front <u>50/50</u> Tag Axle: _____ 1 st Axle: <u>60/60</u> 2 nd Axle: <u>40/40</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 7 <u>8</u> 9 10			
Comments: <u>NO CGL</u>			
Other Comments: <u>SMALL Power Steering LEAKS</u>			

Inspector Print: STEVE KIRCHAG

Date: 8-27-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***

