

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 10/10

Stock Number: 891619

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2019 Make: Freightliner Model: Cascadia Vin #: KH9547

Engine: Make: Detroit Model: DIV5 HP: 475

Odometer Reading: 595,348 ECM Reading: 595,349

Task	Yes	No	Comments
Does the Truck Start?	☒	☐	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	☒	☐	
Does the truck have the Emission Deleted?	☐	☒	
Does the Transmission operate in all gears?	☒	☐	
Does the Air load in normal time?	☒	☐	
Are there any fluid leaks?	☐	☒	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	☐	☒	
Is the oil pressure at idle within OEM specs?	☒	☐	
Is blow-by present?	☐	☐	MAJOR or MINOR
Do you see oil in the coolant?	☒	☐	
Pressure check the cooling system	☒	☐	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	☒	☐	Rate (1-10): _____

Brake Lining: Front R: 20 26 Tag Axle R: _____ L: _____ 1st Axle R: 30 L: 30 2nd Axle R: 20 L: 26

Tire Tread Percentage: Front: 2/3 Tag Axle: _____ 1st Axle: 30/30 2nd Axle: 30/30

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NO CEL

Other Comments: _____

Inspector Print: STEVE FURMAN

Date: 9-2-25

Inspector Signature: Steve Furman

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***