

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

gray

Auction Date: 10/10

Stock Number: 89744

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS ***

*** This is NOT A WARRANTY! ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Peterbilt Model: 579 Vin #: 356092

Engine: Make: PACCAR Model: MX13 HP: 500

Odometer Reading: 1,049,700 ECM Reading: 1,049,696

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?			
Does the Air load in normal time?			
Are there any fluid leaks?			OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?			
Is the oil pressure at idle within OEM specs?			
Is blow-by present?			MAJOR or MINOR
Do you see oil in the coolant?			
Pressure check the cooling system			PASS or FAIL
Is the clutch in good operating condition?			Rate (1-10): _____

Brake Lining: Front R: 40 L: 40 Tag Axle R: _____ L: _____ 1st Axle R: 40 L: 40 2nd Axle R: 40 L: 40

Tire Tread Percentage: Front: 30/30 Tag Axle: _____ 1st Axle: 50/50 2nd Axle: 50/50

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

CEL ON - STOP ENGINE LIGHT &

Other Comments:

DC RATE DUE TO BAD QUALITY SENSOR (Def injector)

Inspector Print: Steve Krueger

Date: 9.4.25

Inspector Signature: Steve Krueger

*** This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***