

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 10/10

Stock Number: 89990

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2019 Make: Peterbilt Model: 579 Vin #: 604998

Engine: Make: Commins Model: X15 HP: 505

Odometer Reading: 697,655 ECM Reading: 697,657

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?	<u>X</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>(X)</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>(X)</u>		Rate (1-10): <u>6</u>

Brake Lining: Front R: Disc L: _____ Tag Axle R: _____ L: _____ 1st Axle R: Disc L: _____ 2nd Axle R: Disc L: _____

Tire Tread Percentage: Front: 50/50 Tag Axle: _____ 1st Axle: 50/50 2nd Axle: 50/50

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10 6

Comments:

NO CEL

Other Comments: _____

Inspector Print: SPENCER KIRWAN

Date: 9-15-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***