

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 10-10

Stock Number: 91133

Lot Number: \_\_\_\_\_

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2022 Make: Peterbilt Model: 579 Vin #: 781760

Engine: Make: Cummins Model: X15 HP: \_\_\_\_\_

Odometer Reading: 179,188 ECM Reading: 403,415

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or FAIL
Is the clutch in good operating condition?		<u>Auto</u>	Rate (1-10): _____

Brake Lining: Front R: CORCOS L: \_\_\_\_\_ Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: 70 L: 70 2<sup>nd</sup> Axle R: 60 L: 60

Tire Tread Percentage: Front: 90/90 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 90/90 2<sup>nd</sup> Axle: 90/90

Comments: \_\_\_\_\_

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: \_\_\_\_\_

NO CEL

Other Comments: \_\_\_\_\_

Inspector Print: SP5 Kandi

Date: 10-1-25

Inspector Signature: John Paul

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*

0701  
8610

001187

pra

11/10/1979

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000

1000