HESS AUCTIONEETS, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493

Fax: 717-427-1665



Auction Date: 10110 Stock Number: 89102 Lot Number:

HESS REPORT SHEET

*** ALL Trucks are For Sale AS IS, WHERE IS *** *** This is **NOT A WARRANTY!** ***

| Truck Type (Circle one): Sleeper / Daycab/ Joc | key / Dump / B | ox / Flatbed / Reefer/ Chassi | s / Other: |
|--|----------------|-------------------------------|----------------|
| Year: 2020 Make: Freightline | lodel: TILO | 428T Vin #: LW | 1448 |
| Engine: Make: | Model: | DD13 HP: 418 | 2_ |
| Odometer Reading: 577,266 ECM Reading: 3,225 | | | |
| Task Ye | es No | Comments | |
| Does the Truck Start? | | Jump Start: YES o NO | |
| Does the motor idle and run normally? | > | | |
| Does the truck have the Emission Deleted? | 7 | | |
| Does the Transmission operate in all gears? | 1 | | |
| Does the Air load in normal time? | V | | |
| Are there any fluid leaks? | × | OIL or COOLANT | MAJOR or MINOR |
| Do you see coolant in the oil? | کر | | |
| Is the oil pressure at idle within OEM specs? | | | |
| Is blow-by present? | | MAJOR or MINOR | |
| Do you see oil in the coolant? | X | | |
| Pressure check the cooling system | | PASS or FAIL | |
| Is the clutch in good operating condition? | AND | Rate (1-10): | |
| Brake Lining: Front R: Tag Axle R: L: 1st Rie R: L: 2nd Axle R: L: | | | |
| Tire Tread Percentage: Front: Tag Axle: 1st Axle: 50/500 nd Axle: | | | |
| Comments: | | | |
| Cosmetic Condi | tion: Rate 1 2 | 2 3 4 5 6 7 8 9 10 | |
| Comments: | SEL | | |
| Other Comments: | | | |
| OF In land | | 16.2.3 | |

Inspector Print:

Date: 10'3-00

Inspector Signature:

*** This report is performed of a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***