

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Recd

Auction Date: ~~02/22~~ 10/10  
Stock Number: 91182  
Lot Number: \_\_\_\_\_

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

| Truck Type (Circle one): Sleeper / Daycab / Jockey <u>(Dump)</u> / Box / Flatbed / Reefer / Chassis / Other: _____                               |          |                             |                               |
|--------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------------------|-------------------------------|
| Year: <u>2016</u> Make: <u>VOIVO</u> Model: <u>VHD 4</u> Vin #: <u>957022</u>                                                                    |          |                             |                               |
| Engine: Make: <u>Volvo</u> Model: <u>D13</u> HP: <u>405</u>                                                                                      |          |                             |                               |
| Odometer Reading: <u>398,662</u>                                                                                                                 |          | ECM Reading: <u>398,663</u> |                               |
| Task                                                                                                                                             | Yes      | No                          | Comments                      |
| Does the Truck Start?                                                                                                                            | <u>X</u> |                             | Jump Start: YES or <u>NO</u>  |
| Does the motor idle and run normally?                                                                                                            | <u>X</u> |                             |                               |
| Does the truck have the Emission Deleted?                                                                                                        |          | <u>X</u>                    |                               |
| Does the Transmission operate in all gears?                                                                                                      | <u>X</u> |                             |                               |
| Does the Air load in normal time?                                                                                                                | <u>X</u> |                             |                               |
| Are there any fluid leaks?                                                                                                                       |          | <u>X</u>                    | OIL or COOLANT MAJOR or MINOR |
| Do you see coolant in the oil?                                                                                                                   |          | <u>X</u>                    |                               |
| Is the oil pressure at idle within OEM specs?                                                                                                    | <u>X</u> |                             |                               |
| Is blow-by present?                                                                                                                              |          | <u>X</u>                    | MAJOR or MINOR                |
| Do you see oil in the coolant?                                                                                                                   |          | <u>X</u>                    |                               |
| Pressure check the cooling system                                                                                                                | <u>X</u> |                             | <u>PASS</u> or FAIL           |
| Is the clutch in good operating condition?                                                                                                       |          | <u>Auto</u>                 | Rate (1-10): _____            |
| Brake Lining: Front R: <u>Disc</u> L: _____ Tag Axle R: <u>60</u> L: <u>60</u> 1st Axle R: <u>Disc</u> L: _____ 2nd Axle R: <u>Disc</u> L: _____ |          |                             |                               |
| Tire Tread Percentage: Front: <u>20/70</u> Tag Axle: <u>20/70</u> 1st Axle: <u>20/70</u> 2nd Axle: <u>20/70</u>                                  |          |                             |                               |
| Comments: _____                                                                                                                                  |          |                             |                               |
| Cosmetic Condition: Rate 1 2 3 4 5 6 <u>0</u> 8 9 10                                                                                             |          |                             |                               |
| Comments: <u>NO CEL</u>                                                                                                                          |          |                             |                               |
| Other Comments: <u>ABS LIGHT</u> <u>VEC SENSOR FAULT</u>                                                                                         |          |                             |                               |

Inspector Print: Steve Kinnick

Date: 9-29-25

Inspector Signature: Steve Kinnick

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*