

Black

Auction Date: 12/12

Stock Number: 91380

Lot Number: _____

HESS REPORT SHEET

*** ALL Trucks are For Sale **AS IS, WHERE IS** ***

*** This is **NOT A WARRANTY!** ***

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____

Year: 2016 Make: Peterbilt Model: 337 Vin #: 338077

Engine: Make: PACCAR Model: PX9 HP: 260

Odometer Reading: 620,538 ECM Reading: 620,539

Task	Yes	No	Comments
Does the Truck Start?	<u>I</u>		Jump Start: YES or NO
Does the motor idle and run normally?	<u>I</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>I</u>		
Does the Air load in normal time?	<u>I</u>		
Are there any fluid leaks?	<u>I</u>		<u>OIL</u> or COOLANT MAJOR or <u>MINOR</u>
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>I</u>		
Is blow-by present?	<u>I</u>		MAJOR or <u>MINOR</u>
Do you see oil in the coolant?		<u>I</u>	
Pressure check the cooling system	<u>I</u>		<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____

Brake Lining: Front R: DISC L: _____ Tag Axle R: _____ L: _____ 1st Axle R: DISC L: _____ 2nd Axle R: _____ L: _____

Tire Tread Percentage: Front 8/50 Tag Axle: _____ 1st Axle: 7/70 2nd Axle: _____

Comments: _____

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments: NO CEL

Other Comments: _____

Inspector Print: STAR KUNAGE

Date: 10-24-25

Inspector Signature: [Signature]

*** This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way ***