

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 12/12  
Stock Number: 91466  
Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale **AS IS, WHERE IS** \*\*\*

\*\*\* This is **NOT A WARRANTY!** \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2015 Make: MACK Model: CX4613 Vin #: 049722

Engine: Make: MACK Model: MP8 HP: 445

Odometer Reading: 589,567 ECM Reading: 589,569

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>Auto</u>

Brake Lining: Front R: DISC L: \_\_\_\_\_ Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: DISC L: \_\_\_\_\_ 2<sup>nd</sup> Axle R: DISC L: \_\_\_\_\_

Tire Tread Percentage: Front 30/30 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 30/30 2<sup>nd</sup> Axle: 50/50

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

NO OIL

Other Comments: \_\_\_\_\_

Inspector Print: SPRUE KUMAR

Date: 11-3-25

Inspector Signature: [Signature]

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*