## Mess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: Dec 38
Stock Number: 91480

Lot Number:

## **HESS REPORT SHEET**

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Year: 2020 Make: VOLVO	Model: <u></u>	NL	860 Vin #: 233365	her:
Engine: Make: Vocal	<u> </u>	∕lodel:	D13 HP: 483	
Odometer Reading: 586,05	<i>76</i>	ECN	M Reading: <u>586, 098</u>	
Task	Yes	No	Jump Start: YES or NO	
Does the Truck Start?	$\sim$		Jump Start, 173 & 189	
Does the motor idle and run normally?	0			
Does the truck have the Emission Deleted?		$\lambda$		
Does the Transmission operate in all gears?	X	100		Ø
Does the Air load in normal time?	<b>X</b>		COLANT	MAJOR or MINOR
Are there any fluid leaks?	All to	×	OIL or COOLANT	WIAJOR OF WINVOR
Do you see coolant in the oil?		X		
Is the oil pressure at idle within OEM specs?	7			
Is blow-by present?		7	MAJOR or MINOR	
Do you see oil in the coolant?		X		
Pressure check the cooling system	1		PASS or FAIL	
Is the clutch in good operating condition?	Aut	6	Rate (1-10):	
Brake Lining: Front R: 50 L: 58 Tag Axle R  Tire Tread Percentage: Front: 40 Logo Tag Axle:	1 <sup>st</sup>	1 <sup>st</sup> Axle: <b>2</b>	Axle R: 10 L. 10 2 <sup>nd</sup> Axle R: 1	40 L: 40
Comments:				
Cosmetic Co	ondition: R		2 3 4 5 6 7 8 9 10	
Other Comments:				

Inspector Signature:

\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*