

**Hess Auctioneers, LLC.**

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 12/12  
 Stock Number: 91450  
 Lot Number: \_\_\_\_\_

**HESS REPORT SHEET**\*\*\* ALL Trucks are For Sale **AS IS, WHERE IS** \*\*\*\*\*\* This is **NOT A WARRANTY!** \*\*\*

Truck Type (Circle one): <u>Sleeper</u> / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: _____			
Year: <u>2020</u> Make: <u>VOLVO</u> Model: <u>VNL 860</u> Vin #: <u>233378</u>			
Engine: Make: <u>VOLVO</u> Model: <u>D13</u> HP: <u>455</u>			
Odometer Reading: <u>622,280</u>		ECM Reading: <u>622,282</u>	
Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>PASS</u> or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Rate (1-10): <u>Auto</u>
Brake Lining: Front R: <u>70</u> L: <u>70</u> Tag Axle R: _____ L: _____ 1 <sup>st</sup> Axle R: <u>50</u> L: <u>50</u> 2 <sup>nd</sup> Axle R: <u>50</u> L: <u>50</u>			
Tire Tread Percentage: Front: <u>60/60</u> Tag Axle: _____ 1 <sup>st</sup> Axle: <u>70/70</u> 2 <sup>nd</sup> Axle: <u>50/50</u>			
Comments: _____			
Cosmetic Condition: Rate 1 2 3 4 5 6 <u>7</u> 8 9 10			
Comments: <u>NO CEL</u>			
Other Comments: _____			

Inspector Print: STEVE KIRKAGEDate: 11-6-25Inspector Signature: [Signature]\*\*\* This report is performed as a guide for our buyers. This report is **NOT** a warranty and **DOES NOT** in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*