

# Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

Auction Date: 12/12

Stock Number: 91453

Lot Number: \_\_\_\_\_

White

White

## HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one) Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer / Chassis / Other: \_\_\_\_\_

Year: 2022 Make: VOLVO Model: VNL860 Vin #: 605995

Engine: Make: VOLVO Model: D13 HP: 455

Odometer Reading: 594,225 ECM Reading: 594,227

Task	Yes	No	Comments
Does the Truck Start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the truck have the Emission Deleted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Does the Transmission operate in all gears?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Does the Air load in normal time?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Are there any fluid leaks?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Is the oil pressure at idle within OEM specs?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Is blow-by present?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	MAJOR or MINOR
Do you see oil in the coolant?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Pressure check the cooling system	<input checked="" type="checkbox"/>	<input type="checkbox"/>	PASS or FAIL
Is the clutch in good operating condition?	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Rate (1-10): <u>Auto</u>

Brake Lining: Front R: 50 L: 50 Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: 60 L: 60 2<sup>nd</sup> Axle R: 70 L: 70

Tire Tread Percentage: Front: 50/60 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 70/70 2<sup>nd</sup> Axle: 60/60

Comments:

Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10

Comments:

No CEL

Other Comments: \_\_\_\_\_

Inspector Print: Steve Knapf

Date: 11-7-25

Inspector Signature: Steve Knapf

\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*