

Hess Auctioneers, LLC.

1451 River Road - PO Box 10 - Marietta, PA 17547

Phone: 1-866-511-2493 Fax: 717-427-1665

White

Auction Date: 12/12  
Stock Number: 91457  
Lot Number:

HESS REPORT SHEET

\*\*\* ALL Trucks are For Sale AS IS, WHERE IS \*\*\*

\*\*\* This is NOT A WARRANTY! \*\*\*

Truck Type (Circle one): Sleeper / Daycab / Jockey / Dump / Box / Flatbed / Reefer/ Chassis / Other: \_\_\_\_\_  
Year: 2019 Make: VOLVO Model: VNL860 Vin #: 211973  
Engine: Make: VOLVO Model: D13 HP: 465  
Odometer Reading: 548,470 ECM Reading: 548,472

Task	Yes	No	Comments
Does the Truck Start?	<u>X</u>		Jump Start: YES or <u>NO</u>
Does the motor idle and run normally?	<u>X</u>		
Does the truck have the Emission Deleted?		<u>X</u>	
Does the Transmission operate in all gears?	<u>X</u>		
Does the Air load in normal time?	<u>X</u>		
Are there any fluid leaks?		<u>X</u>	OIL or COOLANT MAJOR or MINOR
Do you see coolant in the oil?		<u>X</u>	
Is the oil pressure at idle within OEM specs?	<u>X</u>		
Is blow-by present?		<u>X</u>	MAJOR or MINOR
Do you see oil in the coolant?		<u>X</u>	
Pressure check the cooling system	<u>X</u>		PASS or <u>FAIL</u>
Is the clutch in good operating condition?	<u>Auto</u>		Rate (1-10): _____

Brake Lining: Front R: 50 L: 50 Tag Axle R: \_\_\_\_\_ L: \_\_\_\_\_ 1<sup>st</sup> Axle R: 50 L: 50 2<sup>nd</sup> Axle R: 60 L: 60  
Tire Tread Percentage: Front: 70/70 Tag Axle: \_\_\_\_\_ 1<sup>st</sup> Axle: 70/70 2<sup>nd</sup> Axle: 70/70  
Comments: \_\_\_\_\_  
Cosmetic Condition: Rate 1 2 3 4 5 6 7 8 9 10  
Comments: CEL ON  
Other Comments: \_\_\_\_\_

Inspector Print: STEVE K... Date: 11-7-25

Inspector Signature: [Signature]  
\*\*\* This report is performed as a guide for our buyers. This report is NOT a warranty and DOES NOT in any way hold Hess Auctioneers, LLC or its agents or its employees liable in any way \*\*\*